

TWR-17543, Vol. VII
ECS 1012

FLIGHT SET 360T004 (STS-30) FIELD JOINT
PROTECTION SYSTEM FINAL REPORT

20 September 1989

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No. NAS8-30490
DR. No. 5-3 Type 2
WBS.No. 4B102 10 03

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

(NASA-CR-183829) FLIGHT SET 360T004
(STS-30) FIELD JOINT PROTECTION SYSTEM,
VOLUME 7 Final Report (Thiokol Corp.) 65 p

N90-14280

CSCD 21H

Unclass

G3/20 0251582

TWR-17543 Vol. VII
Flight Set 360T004 (STS-30)
Field Joint Protection System Final Report
Volume 7
Final Report

Prepared by:

Elgie Hale
Elgie Hale
Component Design

Approved by:

L. B. Whidden
L. B. Whidden, Supervisor
Ignition, Instr. and Elec.

J. M. Seiler
J. Seiler
Project Engineering

T. Olsen
T. Olsen
Certification Planning

G. Stephens
G. Stephens
Program Manager

S. R. Graves
S. R. Graves, Manager
Nonmetallic Component Design

R. Larsen
R. Larsen
Safety

M. Loosle
M. Loosle
Reliability

P. C. Lydeck 9-27-89
Release
ECS 1012

TABLE OF CONTENTS

1.0	INTRODUCTION	1
2.0	OBJECTIVES	1
3.0	CONCLUSIONS AND RECOMMENDATIONS	2
4.0	RESULTS/DISCUSSIONS	3
4.1	Heater Control System	3
4.2	Post-Flight Inspection of the Joint Protection System	3
4.2.1	Moisture Seal	3
4.2.2	Cork External Insulation	4
4.2.3	Heaters and Sensors	5
4.2.4	Heater Power and Sensor Cables	6
4.2.5	Igniter Heater	6
Appendix A	A-1

FIGURES

Figure 1	Field Joint Protection Configuration	7
Figure 2	Igniter Joint Heater Configuration	8
Figure 3	RSRM Case Configuration and Relationship	9
Figure 4	Crack in Cork on Right Toward Field Joint	10
Figure 5	Void under Crack in Cork, Right Toward Field Joint	11
Figure 6	Debond under Leading Edge, Left Aft Field Joint	12
Figure 7	Left SRM Fwd Field Joint Temperature	13
Figure 8	Right SRM Fwd Field Joint Temperature	14
Figure 9	Left SRM Cntr Field Joint Temperature	15
Figure 10	Right SRM Cntr Field Joint Temperature	16
Figure 11	Left SRM Aft Field Joint Temperature	17
Figure 12	Right SRM Aft Field Joint Temperature	18
Figure 13	Left SRM Igniter Joint Temperatures	19
Figure 14	Right SRM Igniter Joint Temperatures	20

LIST OF TABLES

Table 1	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	21
Table 2	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	22
Table 3	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	23
Table 4	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	24
Table 5	Observation Clarification Form	25
Table 6	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	26
Table 7	Field Joint External Insulation Condition - Evaluation Checkoff Worksheet	27
Table 8	Post-Flight Observation Record (Supplement 3)	28
Table 9	Post-Flight Observation Record (Supplement 3)	29
Table 10	Observation Clarification Form	30
Table 11	Post-Flight Observation Record (Supplement 1)	31
Table 12	Post-Flight Observation Record (Supplement 1)	32
Table 13	Post-Flight Observation Record (Supplement 2)	33
Table 14	Post-Flight Observation Record (Supplement 2)	34
Table 15	Post-Flight Observation Record (Supplement 2)	35
Table 16	Post-Flight Observation Record (Supplement 2)	36
Table 17	Post-Flight Observation Record (Supplement 2)	37
Table 18	Post-Flight Observation Record (Supplement 2)	38
Table 19	Post-Flight Observation Record (Supplement 1)	39
Table 20	Post-Flight Observation Record (Supplement 1)	40
Table 21	Post-Flight Observation Record (Supplement 2)	41
Table 22	Post-Flight Observation Record (Supplement 2)	42
Table 23	Post-Flight Observation Record (Supplement 2)	43
Table 24	Post-Flight Observation Record (Supplement 2)	44
Table 25	Post-Flight Observation Record (Supplement 2)	45
Table 26	Field Joint Heater Cable External Insulation Condition - Evaluation Checkoff Worksheet	46
Table 27	Field Joint Heater Cable External Insulation Condition - Evaluation Checkoff Worksheet	47
Table 28	Igniter Heater Installation Condition - Evaluation Checkoff Worksheet	48
Table 29	Igniter Heater Component - Evaluation Checkoff Worksheet	49

ACRONYMS

JPS Joint Protection System

RSRM Redesigned Solid Rocket Motor

RTD Resistance Temperature Device

TPS Thermal Protection System

PEEP Post-Flight Engineering and Evaluation Plan

PRs Problem Reports

DWV Dielectric Withstanding Voltage

MAB Malfunction Analysis Branch

ABSTRACT

This report contains the prelaunch functioning data of the Joint Protection Systems (JPS) used on STS-30. Also included is the post-flight condition of the JPS components following the launch and recovery of the two RSRM boosters. The JPS components are:

1. Field Joint Heaters
2. Field Joint Sensors
3. Field Joint Moisture Seal
4. Moisture Seal Kevlar Retaining Straps
5. Field Joint External Insulation
6. Vent Valve
7. Power Cables
8. Igniter Heater

1.0 INTRODUCTION

Space Transportation System (STS-30) was launched from KSC on 4 May 1989. Two of the Redesigned Solid Rocket Motors (RSRM) were part of the launch system and are designated by RSRM-4A and RSRM-4B. The three field joints of both motors (total of six field joints) were protected by the Joint Protection Systems (JPS) (see Figure 1). The igniter heater was mounted on the igniter flange (see Figure 2). Figure 3 identifies the RSRM case configuration. The field joint heaters were turned on at L-8 hours and the igniter heater at L-24 hours to assure the joint O-ring and igniter seal temperatures were within the launch commit temperatures at the time of RSRM ignition. The purpose of the moisture seal is to prevent entry of rain into the joint while on the pad. The cork insulation provides thermal protection for the JPS during flight.

Following booster separation and splashdown, the motors were recovered and taken to hanger AF for inspection and disassembly. This inspection was performed per Post-Flight Engineering and Evaluation Plan (PEEP) TWR-16475, Vol. VII which outlines the basic evaluations to be performed at KSC Hanger AF.

2.0 OBJECTIVES

The objective of this report is to document the performance of the JPS and igniter heaters on the pad and the post-flight condition of the JPS

components. This document will also discuss all observations which were written up as Squawks and/or Problem Reports (PRs).

The following objectives of TWR-19071, Morton Thiokol, Inc. Engineering Requirements Document for RSRM Typical Flight, are addressed in this report: (Numbers in parenthesis identify CEI specification paragraphs).

J. Certify the performance of the field joint heater and sensor assembly so that it maintains the case field joint at 75 °F minimum. Field joints shall not exceed 130 °F (3.2.1.11.a).

K. Certify that each field joint heater assembly meets all performance requirements (3.2.1.11.1.2).

3.0 CONCLUSIONS AND RECOMMENDATIONS

The JPS heaters performed per specification and maintained the field joint temperatures within the required temperature range at the time of motor ignition (3.2.1.11.a).

The LH Forward Field Joint Secondary Heater failed Dielectric Withstanding Voltage (DWV) test during the joint closeout prior to launch. This heater was not used since the primary heater functioned properly and maintained the required temperature. Post-test inspection revealed that pin A of the heater power cable was shorted to the connector shell.

Design changes have been implemented to resolve the heater power cable problem.

All field joint heater assemblies met all of the performance requirements (3.2.1.11.1.2).

4.0 RESULTS/DISCUSSIONS

4.1 Heater Control System

The KSC field joint heater temperature control system operated with a control band of 2 °F (set point temperature +/- 1 degree). Temperature expansions outside of this range were apparently the result of noise in the data system. The four temperature sensors at each field joint were continuously monitored and the coldest sensor was automatically selected for temperature control. The igniter control system operated within a control band of ± 5 °F. Both systems maintained the joint temperature within the required limits.

4.2 Post-Flight Inspection of the Joint Protection System

Evaluations of the JPS indicated the system performed as designed during flight.

4.2.1 Moisture Seal

A test of the vent valves on the STS-30 was conducted in the VAB after assembly which verified that all vent valves were closed. This confirms

that the vent valves would not become a source of entry of rain water into the field joint while on the pad.

4.2.2 Cork External Insulation

All of the cork and ablative compound on the field joints was intact. Occasional pitting of the cork and paint was observed on those aft surfaces of cork that were exposed to nozzle severance and splashdown debris. Areas of darkened paint accompanied with blisters were also observed.

A crack in the extruded cork was found during open assessment on the right-hand forward field joint (see Figure 4). The exposed length ran 4.0 inches. The crack was approximately twice that size in the cork, but was bridged over with Hypalon paint. Dissection revealed a void under the crack running 5.0 inches circumferentially by 1.8 inches axially by 0.3 to 0.4 inch deep radially (see Figure 5). The void coincided with a carved out area in the cork at the 30-degree trunnion location.

Tables 1 through 7 are the post-test evaluation checkoff worksheets for the cork external insulation on the six field joints.

The aft and center field joints on the left-hand motor were dissected to assess the bond quality of the leading edge. The aft field joint had three

significant voids with areas of 15, 60* and 58* in.². The center field joint had seven significant voids with areas of 34*, 11, 22*, 5*, 7, 4 and 14* in.². A typical area (34 in.² intermittently) is shown in Figure 6. Tables 8 through 10 further document these voids.

The aft and center field joints on the left-hand motor were dissected to assess the bond quality between the extruded cork and the EPDM moisture seal/Kevlar straps. As seen in the past, large areas of void/unbond were seen between the Kevlar straps and the cork, especially on the forward straps. This appears to be the result of entrapped air forming a large, nearly full circumference void, between the Kevlar strap and the extruded cork. Other voids were also documented. Tables 11 through 25 document the status of the vent holes which were drilled in the cork.

4.2.3 Heaters and Sensors

The heaters and sensors functioned normally and maintained the specified joint temperatures.

The heaters and the sensor assemblies were not available for inspection except as shredded pieces after removal by water laser. The pieces examined showed no signs of overheating, discoloration, or delamination.

*intermittent voids

Figures 7 through 9 are plots of the temperature of the four RTDs of each of the three field joints of the left SRM and Figures 10 through 12 are plots of the RTDs of the right SRM. The ambient temperature air is overlaid on the temperature plots. TWR 17543 provides an explanation for some of the observed temperature excursions.

The post-flight inspection of the left-hand secondary heater system isolated the problem to the cable. The conductor on pin A was shorted to the connector back shell. This section of cable was sent to the Malfunction Analysis Branch (MAB) where an investigation has been completed. The investigation report, MAB104, is attached as Appendix A.

4.2.4 Heater Power and Sensor Cables

All of the cables of the JPS system were embedded in K5NA. The K5NA was visually inspected and found to have survived the flight in excellent condition. There was no evidence of voids or missing material, debonds, charred material, or impact damage. Tables 26 and 27 are the post-test evaluation worksheets for the heater cables.

4.2.5 Igniter Heater

The igniter heater installation on each motor was intact and secure. Figures 13 and 14 are the plots of the temperature at the igniter adapter. Table 28 is the evaluation checkoff worksheet for the igniter heater installation. Table 29 is the evaluation checkoff worksheet for the igniter heater components.

DISTRIBUTION

<u>Recipient</u>	<u>Mail Stop</u>	<u>Copies</u>
E. Hale	L62	1
B. Whidden	L62	1
S. Graves	L62	1
J. Seiler	L10	1
R. Larsen	851	1
T. Olsen	L31	1
M. Loosle	851	1
T. Morgan	L10	1
S. Olson	L35	1
C. Whitworth	L40	1
Print Crib	K23B	5
Vault	L23E	5

MORTON THIokol, INC.

Aerospace Group

Space Operations

APPENDIX A

Malfunction Analysis Branch Report
MAB-104-89

SRB Forward Joint Heater Power Cable Failure Analysis

REVISION _____

FORM TC 7994-310 (REV 2-88)

DOC NO.	TWR-17543	VOL
SEC	PAGE	A-1

NASA
DIRECTOR OF ENGINEERING DEVELOPMENT
DIRECTOR, MECHANICAL ENGINEERING
MATERIALS SCIENCE LABORATORY
MALFUNCTION ANALYSIS BRANCH
DM-MSL-3, ROOM 2217, O&C BUILDING
KENNEDY SPACE CENTER, FLORIDA 32899

MAB-104-89

JUNE 23, 1989

SUBJECT: SRB Forward Joint Heater Power Cabling Failure
Analysis

1.0 FOREWORD

- 1.1 Prior to the flight of STS 30R, the forward joint redundant heater failed a ramped 1500 volt DC Dielectric Withstand Voltage Test (DWV).
- 1.2 Post flight testing indicated that connector X22W802/P1 was most likely the cause of the preflight anomaly although other cable segments indicated faults. All cable segments identified as anomalous were sent by Lockheed Space Operations Company (LSOC) personnel to the Malfunction Analysis Branch (MAB) for evaluation.

2.0 INVESTIGATIVE PROCEDURES AND RESULTS

- 2.1 It was suspected that the cabling submitted to the MAB was contaminated with salt water and salt residue as a result of the SRB flight recovery operation. The subject cabling was subjected to a drying procedure which consisted of being placed in an environmental chamber at reduced pressure. This depressurized condition was maintained for several hours. The cables were then submerged in demineralized water and thoroughly rinsed of salt residue. The cables were again submitted to vacuum.
- 2.2 Analysis of the cables after the drying process indicated that only the cable segment containing connector X22W802/P1 had a verifiable anomaly.

This anomaly was a high resistance path from pin "A" to Shield. This segment of cable is shown in Figure 1.

- 2.3 Connector X22W802/P1 and connector X22A50 P2/J2 were fluoroscopically examined. No anomalies were noted.
- 2.4 The cable segment containing connector X22W802/P1 was evaluated using both a Hewlett Packard (HP) 3478 multimeter (accurate to 30 Megohms) and a General Radio (GENRAD) Megohm Bridge model 1044-A. Readings from the GenRad bridge indicated that at voltage levels up to 200 volts DC the cable anomaly measured slightly greater than 3.5 Megohms. Above 500 volts DC the anomaly indicated less than 1 Kohm.
- 2.5 Connector X22A50/P2 was then removed from the cable assembly and the presences of the anomaly checked as described in paragraph 2.4.
- 2.6 While observing the indication of the anomaly, using the previously described test equipment, the cabling was flexed/manipulated in an attempt to isolate the area of concern. This procedure indicated that the cabling below the "Y" (towards connector X22A50/P1) was unrelated to the anomaly. This segment of cabling was separated and the presence of the anomaly again confirmed.
- 2.7 The remaining segment of cabling was again fluoroscoped looking closely for indications of some type wire-to-shield anomaly. No irregularities were noted.
- 2.8 At this point a careful dissection of the remaining cable assembly was undertaken. Figure 2 depicts the result of shield removal. After the shield was removed the anomaly was again verified. The top backshell nut was removed without affecting the anomaly and all unrelated conductors were severed (See Figure 3).
- 2.9 The connector was then examined fluoroscopically and a typical radiographic view is shown in Figure 4. Note that the wire conductor corresponding to pin "A" appears to be pressed against the inner wall of the backshell. The lower view in Figure 4 shows the inner backshell highlighted.

- 2.10 The remainder of the backshell was removed exposing the underlying Stycast material and conductors. This area was examined using a low power stereomicroscope. Figure 5 illustrates the anomaly located against the inner wall of the backshell. Figure 6 shows a magnified view of the anomaly and the arrow in the lower view indicates a melted strand of the wire conductor.

3.0 DISCUSSION

- 3.1 The anomaly examination described in paragraph 2.10 indicated two items of interest. The first of these items was that the area of concern appeared slightly charred or carbonized. This anomaly is most likely related to the number of times the connector (and pin "A" in particular) was exposed to DWV.
- 3.2 The second item of interest related to the actual surface geometry of the anomaly. It appears that a thin (flap) segment of the conductor insulation was peeled back as a result of insertion into the connector backshell. This anomaly may have been caused by a nick in the insulation (from assembly or handling) which was then scraped against the edge of the inner backshell wall. Regardless of the method, the underlying insulation was either thinned or removed exposing the wire conductors. This exposure resulted in failing DWV.

4.0 CONCLUSION


The connector failed DWV due to a manufacturing anomaly. This anomaly consisted of damaged insulation on the conductor corresponding to pin "A" and was fixed (using a Stycast potting compound) against the interior of the connector backshell.

INVESTIGATOR:


LAWRENCE L. LUDWIG

APPROVED:


C. R. DENABURG



ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

FIGURE 1
PHOTOGRAPH OF CABLE SEGMENT "AS RECEIVED".
MAGNIFICATION: 3X




FIGURE 2

PHOTOGRAPH OF THE ANOMALOUS CABLE SEGMENT WITH AND WITHOUT
SHIELD AND OUTER JACKET.

MAGNIFICATION: BOTH 6X

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH



FIGURE 3

PHOTOGRAPH OF ANOMALOUS CONNECTOR WITH UNRELATED CONDUCTORS
REMOVED.

MAGNIFICATION: 0.6X



FIGURE 4

RADIOGRAPHS OF ANOMALOUS CONNECTOR DEPICTING THE POSITION OF
THE CONDUCTOR CORRESPONDING TO PIN "A".

MAGNIFICATION: BOTH 1.5X





FIGURE 5

PHOTOGRAPH OF THE CONNECTOR ANOMALY.
MAGNIFICATION: 1.9X

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH




FIGURE 6

MAGNIFIED VIEW OF THE CONNECTOR ANOMALY.
MAGNIFICATION: UPPER 4.3X
LOWER 14X




Figure 1 Field Joint Protection Configuration




Figure 2 Igniter Joint Heater Configuration




Figure 3 RSRM Case Configuration and Relationship

MORTON THIOKOL INC.

Aerospace Group

Space Operations

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

1 2 3 4 5

SUBJECT: 275-20 ROPS
K.A. F.W. F.W. Jt.

DESCRIPTION: 30°
Tension Load - Wagon Loading

PHOTO: 275-20

DATE: 10/15/64

MORTON THIOKOL INC. Wash. Operations
FORM TC 110



Figure 4 Crack in Cork on Right Toward Field Joint

REVISION _____

FORM TC 7994-310 (REV 2-88)

DOC
NO.
SEC

TWR-17543

VOL

PAGE

10




Figure 5 Void under Crack in Cork, Right Toward Field Joint




Figure 6 Debond under Leading Edge, Left Aft Field Joint




Figure 7 Left SRM Fwd Field Joint Temperature Overlaid with Ambient




Figure 8 Right SRM Fwd Field Joint Temperature Overlaid with Ambient




Figure 9 Left SRM Cntr Field Joint Temperature Overlaid with Ambient




Figure 10 Right SRM Cntr Field Joint Temperature Overlaid with Ambient





Figure 11 Left SRM Aft Field Joint Temperature Overlaid with Ambient


ZERO REF: 2:47 PM EDT (KSC) 4-MAY-1989 (SRB IGN)



LEGEND	
	KMTTA001A (AMBIENT)
	B06T8068A (15 DEG)
	B06T8069A (135 DEG)
	B06T8070A (195 DEG)
	B06T8071A (285 DEG)

*NOTE: T-0: 124:18:47:00 (GMT)
PLOTTED FROM NRT DATA (1 SPM)
ALL REF INSTR BASED ON SRM ORIENTATION
PLOTTED 4-MAY-1989

Figure 12 Right SRM Aft Field Joint Temperature Overlaid with Ambient



•NOTE: T-0: 124:18:47:00 (GMT)
PLOTTED FROM NRT DATA (1 SPM)
ALL REF INSTR BASED ON SRM ORIENTATION
PLOTTED 4-MAY-1989

Figure 13 Left SRM Igniter Joint Temperature Overlaid with Ambient




Figure 14 Right SRM Igniter Joint Temperatures Overlaid with Ambient

Table 1
Field Joint External Insulation Condition - Evaluation Checkoff Worksheet

Inspector(s): Mark Perry

Motor No.: STS-30 Side: ☒ Left ☐ Right Date: 7 May 1989

Field Joint: ☒ Forward (FWD) ☐ Center (CTR) ☐ Aft (AFT)

Component: JPS

I. External Cork Insulation

- A. Voids or Missing Material >0.7 cu.in. (TPSVD)? yes ✓ no
- B. Debonds (DEBND)? yes ✓ no
- C. Charred Material (HTAFF)? yes ✓ no

If any of the above conditions exist, note:

Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)

Notes / Comments

1) K5NA repairs, 1.5 in. diameter, on the leading edge where pull tests were performed pre-flight. (Repairs at 60°, 150°, 240°, and 330°).

2) ~~K5NA~~ Cork repairs were noted at 25° and 120°:




Table 2

REVISION

Table 3

Field Joint External Insulation Condition - Evaluation Checkoff Worksheet


[illegible]

Table 5
Observation Clarification Form

Motor No. STS-30 Inspector(s) Mark Perry Date 7 May 1989
☐ Left (A) ☒ Right (B)
 Segment: ☒ Forward ☒ Forward Center ☐ Aft Center ☐ Aft ☐ Nozzle
 Joint: Forward Field Joint Case End: NA
 Location: Axial (In.) NA Starting Degree NA Ending Degree NA
 Size: Circumferential Width (In.) NA Axial Length (In.) NA
 Radial Distance (In.) NA
 Description: _____


Sketch observation below or attach worksheets and list below. Indicate orientation and dimensions. Show as much detail as necessary to explain the observation.

3) Additional drilled vent holes were noted as follows:
FORWARD SIDE



4) No vent hole pattern was drilled at the 30° trunion location.

5) At the 30° trunion location a depression was found ~~on the trunion~~ (approximately 2.5 inches in diameter) and a crack (0.4 in. in circumference) was on the forward edge. When the depression was hand-pressed, water flowed out of the crack. See the figure below



ORIGINAL PAGE IS
OF POOR QUALITY

REVISION _____

DOC NO. TWR-17543
SEC _____

PAGE 25

Table 6
Field Joint External Insulation Condition - Evaluation Checkoff Worksheet

Inspector(s): <u>Mark Perry</u>																																																							
Motor No.: <u>STS-30</u>			Side: <input type="checkbox"/> Left <input checked="" type="checkbox"/> Right		Date: <u>7 May 1989</u>																																																		
Field Joint: <input type="checkbox"/> Forward (FWD) <input checked="" type="checkbox"/> Center (CTR) <input type="checkbox"/> Aft (AFT)																																																							
Component: <u>JPS</u>																																																							
<p>I. External Cork Insulation</p> <p>A. Voids or Missing Material >0.7 cu.in. (TPSVD)? <u> </u> yes <u> </u> no <input checked="" type="checkbox"/></p> <p>B. Debonds (DEBND)? <u> </u> yes <u> </u> no <input checked="" type="checkbox"/></p> <p>C. Charred Material (HTAFF)? <u> </u> yes <u> </u> no <input checked="" type="checkbox"/></p> <p>If any of the above conditions exist, note:</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th>Condition (Observation Code)</th> <th>Axial Location (Station) (In.)</th> <th>Starting Degree Location (Deg.)</th> <th>Ending Degree Location (Deg.)</th> <th>Circumferential Width (In.)</th> <th>Axial Length (In.)</th> <th>Radial Depth (In.)</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>							Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)																																										
Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)																																																	
<p>Notes / Comments</p> <p>1) K5NA repairs, 1.5 in. diameter, on the leading edge where pull tests were performed pre-flight (Repairs at 60°, 150°, 240°, and 330°).</p> <p>2) Additional drilled vent holes were noted as follows:</p> <div style="margin-top: 20px;"> </div>																																																							

ORIGINAL PAGE IS
OF POOR QUALITY

Table 7
Field Joint External Insulation Condition - Evaluation Checkoff Worksheet

Inspector(s): <u>Mark Perry</u>		
Motor No.: <u>STS-30</u>	Side: <input type="checkbox"/> Left <input checked="" type="checkbox"/> Right	Date: <u>7 May 1989</u>
Field Joint: <input type="checkbox"/> Forward (FWD) <input type="checkbox"/> Center (CTR) <input checked="" type="checkbox"/> Aft (AFT)		
Component: <u>JPS</u>		

I. External Cork Insulation


A. Voids or Missing Material >0.7 cu.in. (TPSVD)?	yes	no	<input checked="" type="checkbox"/>	no
B. Debonds (DEBND)?	yes	no	<input checked="" type="checkbox"/>	no
C. Charred Material (HTAFF)?	yes	no	<input checked="" type="checkbox"/>	no

If any of the above conditions exist, note:

Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)

Notes / Comments

1) KSNA repairs, 1.5 in. diameter, on the leading edge where pull tests were performed pre-flight (Repairs at 60°, 150°, 240°, and 330°).
2) Additional repairs and drilled holes were noted as follows:



ORIGINAL PAGE IS
OF POOR QUALITY

Table 8 Post-Flight Observation Record (Supplement 3)
FIELD JOINT PROTECTION SYSTEM
LEADING EDGE BONDLINE EVALUATION

DATE: 5-8-89
INSPECTORS: Mark Perry
MOTOR NO.: STS-30
JOINT: X AFT CENTER FORWARD
SIDE: X LEFT (A) RIGHT (B)
NOTE: DOCUMENT ALL VOIDS/UNBONDS GREATER THAN 2 SQUARE INCHES AND WITH AN ASPECT RATIO LESS THAN 10 (LENGTH/WIDTH)

CIRC MAXIMUM DIMENSIONS			AVERAGE DIMENSIONS			COMMENTS	
LOC	CIRC AXIAL	RADIAL	CIRC	AXIAL	RADIAL		
20°	30.3	2.25	.05	NA	2.25	.05	Pendritic, Growing toward, 50% VOID AREA
295°	8.4	1.6	.05	NA	1.3	.05	Single Void - w/flat many fingers
268°	13.5	2.3	.05	NA	2.3	.05	Pendritic, No Direction 70% VOID AREA
178°	5.3	2.1	.07	NA	2.0	.05	70% Void, Location of Butt Joint
160°	4.3	1.7	.05	NA	1.5	.05	Several interconnected Fingers
145°	2.2	2.0	.05	NA	1.7	.05	Sketch @ Section & Bond Formed
120°	12.0	2.2	.08	NA	2.0	.05	60% void Area

General Notes:

90 - 20 95% Void Free
0 - 290 90% Void Free - A few voids at 1 in² and less
250 - 200 95% Void Free
200 - 160 90% Void Free
160 - 90 80% Void Free

ORIGINAL PAGE IS
OF POOR QUALITY

Table 9 Post-Flight Observation Record (Supplement 3)
FIELD JOINT PROTECTION SYSTEM
LEADING EDGE BONDLINE EVALUATION

DATE: 5-8-89
INSPECTORS: Mark Perry
MOTOR NO.: STS-30
JOINT: AFT X CENTER X FORWARD

SIDE: X LEFT (A) RIGHT (B)

NOTE: DOCUMENT ALL VOIDS/UNBONDS GREATER THAN 2 SQUARE INCHES AND WITH AN ASPECT RATIO LESS THAN 10 (LENGTH/WIDTH)

CIRC MAXIMUM DIMENSIONS AVERAGE DIMENSIONS
LOC CIRC AXIAL RADIAL CIRC AXIAL RADIAL COMMENTS

260°	25	1.3	0.15	NA	0.6	0.10	Over sensor, in tent that / inter connected
140	33.5	3.2	0.1	NA	3.0	0.05	40% Coat Band / 60% Void - Predictive
120	32	3.5	0.1	NA	3.0	0.05	40% Coat Band / 60% Void - Predictive

Granular
Formed

General Notes

90-40 (One piece of coat) - 99% Void Free

40-5 90% Void Free

5-270 A lot of EA934 NA - to - Paint Failure from chipping - No large voids



240-160 85% Void Free, some Epoxy / Paint Chipping, Thick Bands of Voids over RTD

160-90 40% Void Free

Table 10
Observation Clarification Form

Motor No. STS-30 Inspector(s) Mark Perry Date 8 May 1989
☐ Left (A) ☒ Right (B)
 Segment: ☒ Forward ☒ Forward Center ☐ Aft Center ☐ Aft ☐ Nozzle
 Joint: Forward Field Joint Case End: NA
 Location: Axial (In.) NA Starting Degree 30° Ending Degree 30°
 Size: Circumferential Width (In.) NA Axial Length (In.) NA
 Radial Distance (In.) NA
 Description: _____

Sketch observation below or attach worksheets and list below. Indicate orientation and dimensions. Show as much detail as necessary to explain the observation.


 <p><u>FJPS on the motor</u></p> <ul style="list-style-type: none"> - A 2.5" diameter depression in the cork - A 0.4" circumferential crack through the cork and paint. The paint covered the ends of the cork crack. The cork crack appeared to run 1.3" 	 <p><u>Extruded Cork Off the Motor</u></p> <ul style="list-style-type: none"> - void at depression was 0.3 to 0.4 inch deep (radial)
---	--

ORIGINAL PAGE IS
OF POOR QUALITY

Table 11 Post-Flight Observation Record (Supplement 1)
FIELD JOINT PROTECTION SYSTEM
KEVLAR STRAP BUCKLE VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: 575-30 SIDE: X LEFT (A) RIGHT (B)
JOINT: X AFT CENTER FORWARD
FORWARD BUCKLE
CIRCUMFERENTIAL LOCATION: 137°
AFT BUCKLE
CIRCUMFERENTIAL LOCATION: 134°

Deep Void (0.4 inch)



The aft strap
should be shifted
6 scale inches
to the right to
represent the actual
orientation.




Table 12
Post-Flight Observation Record (Supplement 1)

FIELD JOINT PROTECTION SYSTEM
KEVLAR STRAP BUCKLE VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: ☒ LEFT (A) ☐ RIGHT (B)
JOINT: ☒ AFT ☐ CENTER ☐ FORWARD

FORWARD BUCKLE

CIRCUMFERENTIAL LOCATION: 137

DISTANCE BETWEEN CENTERLINES OF BUCKLE AND HOLE PATTERN: 1"

Buckle Centered at hole 5

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F	No	No		
2F	No	No		
3F	No	Yes		
4F	No	Yes		
5F	No	No		
6F	No	No		
7F	No	No		
8F	No	Yes		
9F	No	No		
10F	No	No		
11F	No	No		

AFT BUCKLE

CIRCUMFERENTIAL LOCATION: 134

DISTANCE BETWEEN CENTERLINES OF BUCKLE AND HOLE PATTERN: 1"

Buckle Centered at hole #7

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1A	No	No		
2A	No	No		
3A	No	No		
4A	No	No		
5A	No	Yes		
6A	No	Yes		
7A	No	No		
8A	No	No		
9A	No	No		
10A	No	No		
11A	No	No		

Table 13 Post-Flight Observation Record (Supplement 2)
FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: ☒ LEFT (A) ☐ RIGHT (B)
JOINT: ☒ AFT ☐ CENTER ☐ FORWARD
CIRCUMFERENTIAL LOCATION: ☒ 30 ☐ 150 ☐ 270





Table 14
Post-Flight Observation Record (Supplement 2)

FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: X LEFT (A) RIGHT (B)
JOINT: X AFT CENTER FORWARD
CIRCUMFERENTIAL LOCATION: 30 X 150 270

DISTANCE BETWEEN CENTERLINES OF TRUNNION AND HOLE PATTERN: N4

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
----------------	---------------------	------------------	--------------	----------

1F				
2F				
3F				
4F				
5F				
6F				
7F				
8F				
9F				
10F				
11F				
1A				
2A				
3A				
4A				
5A				
6A				
7A				
8A				
9A				
10A				
11A				

No hole patterns drilled
Minimum Cork Thickness: 0.25"

ORIGINAL PAGE IS
OF POOR QUALITY

Table 15 Post-Flight Observation Record (Supplement 2)
FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: X LEFT (A) _____ RIGHT (B) _____
JOINT: X AFT _____ CENTER _____ FORWARD _____
CIRCUMFERENTIAL LOCATION: 30 150 X 270





Table 16
Post-Flight Observation Record (Supplement 2)

FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: ☒ LEFT (A) ☐ RIGHT (B)
JOINT: ☒ AFT ☐ CENTER ☐ FORWARD
CIRCUMFERENTIAL LOCATION: ☐ 30 ☐ 150 ☒ 270

DISTANCE BETWEEN CENTERLINES OF TRUNNION AND HOLE PATTERN: 3 "
Center of the trunnion lies below hole # 9

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F	No	No		
2F	No	No		
3F	No	No		
4F	No	No		
5F	No	No		
6F	No	No		
7F	No	No		
8F	No	No		
9F	No	No		
10F	No	No		
11F	No	No		
1A	No	No		
2A	No	No		
3A	No	No		
4A	No	No		
5A	No	No		
6A	No	No		
7A	No	No		
8A	No	No		
9A	No	No		
10A	No	No		
11A	No	No		

ORIGINAL PAGE IS
OF POOR QUALITY

Table 17 Post-Flight Observation Record (Supplement 2)
FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: ☒ LEFT (A) ☐ RIGHT (B)
JOINT: ☒ AFT CENTER FORWARD
CIRCUMFERENTIAL LOCATION: 30 ☒ 150 270

No Hole Patterns Drilled





Table 18
Post-Flight Observation Record (Supplement 2)

FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89

INSPECTORS: Mark Perry, Elgie Hale

MOTOR NO.: STS-30

SIDE: ☒ LEFT (A) ☐ RIGHT (B)

JOINT: ☒ AFT ☐ CENTER ☐ FORWARD

CIRCUMFERENTIAL LOCATION: ☒ 30 ☐ 150 ☐ 270

DISTANCE BETWEEN CENTERLINES OF TRUNNION AND HOLE PATTERN: 0.0 inch

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F	No	No		
2F	No	No		
3F	No	No		
4F	No	No		
5F	No	No		
6F	No	Yes		
7F	No	Yes		
8F	No	No		
9F	No	No		
10F	No	No		
11F	No	No		
1A	No	No		
2A	No	No		
3A	No	No		
4A	No	No		
5A	No	No		
6A	No	No		
7A	No	No		
8A	No	No		
9A	No	No		
10A	No	No		
11A	No	No		

Table 19 Post-Flight Observation Record (Supplement 1)

FIELD JOINT PROTECTION SYSTEM
KEVLAR STRAP BUCKLE VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry
MOTOR NO.: STS-30
JOINT: AFT X CENTER FORWARD RIGHT (R)
SIDE: X LEFT (A)
FORWARD BUCKLE
CIRCUMFERENTIAL LOCATION: 134°
AFT BUCKLE
CIRCUMFERENTIAL LOCATION: 133°




Table 20
Post-Flight Observation Record (Supplement 1)

FIELD JOINT PROTECTION SYSTEM
KEVLAR STRAP BUCKLE VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: X LEFT (A) RIGHT (B)
JOINT: AFT X CENTER FORWARD

FORWARD BUCKLE

CIRCUMFERENTIAL LOCATION: 134°

DISTANCE BETWEEN CENTERLINES OF BUCKLE AND HOLE PATTERN: 0.0"

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F	No	No		
2F	No	No		
3F	No	No		
4F	No	No		
5F	No	No		
6F	No	No		
7F	No	No		
8F	No	Yes	No	} Same Void
9F	No	Yes	No	
10F	No	Yes	No	
11F	No	No		

AFT BUCKLE

CIRCUMFERENTIAL LOCATION: 133°

DISTANCE BETWEEN CENTERLINES OF BUCKLE AND HOLE PATTERN: 0.75"
Centered near hole #7

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1A	No	No		
2A	No	No		
3A	No	No		
4A	No	No		
5A	No	No		
6A	No	No		
7A	No	No		
8A	No	No		
9A	No	No		
10A	Lost Cork Fragment - No voids			
11A	Lost Cork Fragment - No voids			

Table 21 Post-Flight Observation Record (Supplement 2)

**FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT**

DATE: 5-9-89
INSPECTORS: Mark Perry
MOTOR NO.: STS-30
JOINT: AFT X CENTER FORWARD
SIDE: X LEFT (A) RIGHT (B)
CIRCUMFERENTIAL LOCATION: X 30 150 270






Table 22 Post-Flight Observation Record (Supplement 2)
FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: **S-9-89**
INSPECTORS: **Mark Perry**
MOTOR NO.: **STS-30** SIDE: **X** LEFT (A) _____ RIGHT (B) _____
JOINT: _____ AFT **X** CENTER _____ FORWARD _____
CIRCUMFERENTIAL LOCATION: _____ 30 **X** 150 _____ 270



23 Inches of Complete Aft Strap Unbond/Void

Table 23
Post-Flight Observation Record (Supplement 2)

FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elie Hale
MOTOR NO.: STS-30 SIDE: ☒ LEFT (A) ☐ RIGHT (B)
JOINT: ☐ AFT ☒ CENTER ☐ FORWARD
CIRCUMFERENTIAL LOCATION: ☐ 30 ☒ 150 ☐ 270

DISTANCE BETWEEN CENTERLINES OF TRUNNION AND HOLE PATTERN:

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F				NO HOLES DRILLED
2F				
3F				
4F				
5F				
6F				
7F				
8F				
9F				
10F				
11F				
1A				
2A				
3A				
4A				
5A				
6A				
7A				
8A				
9A				
10A				
11A				

MIN. CORK THICKNESS IS .25

ORIGINAL PAGE IS
OF POOR QUALITY

REVISION _____

Table 24 Post-Flight Observation Record (Supplement 2)
FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry
MOTOR NO.: ST5-30
JOINT: X CENTER 30 FORWARD 150 RIGHT (B) X 270
CIRCUMFERENTIAL LOCATION: 30 150 X 270





Table 25
Post-Flight Observation Record (Supplement 2)

FIELD JOINT PROTECTION SYSTEM
HAT BAND TRUNNION VENT HOLE PATTERN ASSESSMENT

DATE: 5-9-89
INSPECTORS: Mark Perry, Elgie Hale
MOTOR NO.: STS-30 SIDE: X LEFT (A) RIGHT (B)
JOINT: AFT X CENTER FORWARD
CIRCUMFERENTIAL LOCATION: 30 150 X 270
Trunnion centered at hole #7 location
DISTANCE BETWEEN CENTERLINES OF TRUNNION AND HOLE PATTERN: 1"

HOLE NUMBER	DRILLED THROUGH?	VOID AT HOLE?	HIT VOID?	COMMENTS
1F	<u>NO</u>	<u>NO</u>		<u>MIN. CORK THICKNESS 0.29"</u>
2F	<u>NO</u>	<u>NO</u>		
3F	<u>NO</u>	<u>NO</u>		
4F	<u>NO</u>	<u>NO</u>		
5F	<u>Yes</u>	<u>NO</u>		
6F	<u>Yes</u>	<u>NO</u>		
7F	<u>Yes</u>	<u>NO</u>		
8F	<u>Yes</u>	<u>NO</u>		
9F	<u>NO</u>	<u>NO</u>		
10F	<u>NO</u>	<u>NO</u>		
11F	<u>NO</u>	<u>NO</u>		
1A	<u>NO</u>	<u>NO</u>		
2A	<u>NO</u>	<u>NO</u>		
3A	<u>NO</u>	<u>NO</u>		
4A	<u>NO</u>	<u>NO</u>		
5A	<u>NO</u>	<u>NO</u>		
6A	<u>NO</u>	<u>NO</u>		
7A	<u>NO</u>	<u>NO</u>		
8A	<u>NO</u>	<u>NO</u>		
9A	<u>NO</u>	<u>NO</u>		
10A	<u>NO</u>	<u>NO</u>		
11A	<u>NO</u>	<u>NO</u>		

Table 26
Field Joint Heater Cable External Insulation Condition - Eval Checkoff Worksheet

Inspector(s): <u>Mark Perry / Ernie Hale</u>						
Motor No.: <u>STS-30</u>			Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)		Date: <u>7 May 1989</u>	
Component: <u>TPS</u>						

I. External Cork Insulation

A. Voids or Missing Material >0.7 cu.in. (TPSVD)?	_____ yes	_____ <input checked="" type="checkbox"/> no	
B. Debonds (DEBND)?	_____ yes	_____ <input checked="" type="checkbox"/> no	
C. Charred (HTAFF)?	_____ yes	_____ <input checked="" type="checkbox"/> no	

II. Cables Debonded (DEBND) if visible? _____ yes _____ ☒ no

If any of the above conditions exist, note:

Segment (FWD, FCS, ACS or AFT)	Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____

Notes / Comments

The forward, forward/center, and aft/center configurations were as shown:

Table 27
Field Joint Heater Cable External Insulation Condition - Eval Checkoff Worksheet



Inspector(s): <u>Mark Perry / Elgie Hale</u>																																																							
Motor No.: <u>STS-30</u>			Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)		Date: <u>7 May 1989</u>																																																		
Component: <u>TPS</u>																																																							
<p>I. External Cork Insulation</p> <p>A. Voids or Missing Material >0.7 cu.in. (TPSVD)? _____ yes <input checked="" type="checkbox"/> no</p> <p>B. Debonds (DEBND)? _____ yes <input checked="" type="checkbox"/> no</p> <p>C. Charred (HTAFF)? _____ yes <input checked="" type="checkbox"/> no</p> <p>II. Cables Debonded (DEBND) if visible? _____ yes <input checked="" type="checkbox"/> no</p> <p>If any of the above conditions exist, note:</p> <table border="1" style="width:100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th>Segment (FWD, FCS, ACS or AFT)</th> <th>Condition (Observation Code)</th> <th>Axial Location (Station) (In.)</th> <th>Starting Degree Location (Deg.)</th> <th>Ending Degree Location (Deg.)</th> <th>Circumferential Width (In.)</th> <th>Axial Length (In.)</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>							Segment (FWD, FCS, ACS or AFT)	Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)																																										
Segment (FWD, FCS, ACS or AFT)	Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)																																																	
<p>Notes / Comments</p> <p>The configurations were as follows:</p> <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="width: 45%;"> <p><u>Aft/Center Segment</u></p>  </div> <div style="width: 45%;"> <p><u>Forward and Forward/Center Segments</u></p>  </div> </div>																																																							

Table 28
Igniter Heater Installation Condition - Evaluation Checkoff Worksheet

Inspector(s): Elgie Hale					
Motor No.:			Side: <input checked="" type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)		Date: 5/7/89
Joint: Igniter (IGN)		Case End: Igniter Adapter (FWD)			Component: JPS

I. Igniter Heater					
A. Unsecure(LOOSE)?	_____ yes		<input checked="" type="checkbox"/> no		
B. Improper position (DISCP)?	_____ yes		<input checked="" type="checkbox"/> no		
II. Cork Insulation					
A. Unsecure(LOOSE)?	_____ yes		<input checked="" type="checkbox"/> no		
B. Improper position (DISCP)?	_____ yes		<input checked="" type="checkbox"/> no		
III. T-Bolt Latch Band Clamp					
A. Unsecure(LOOSE)?	_____ yes		<input checked="" type="checkbox"/> no		
B. Improper position (DISCP)?	_____ yes		<input checked="" type="checkbox"/> no		
IV. Igniter Heater Power Cables					
A. Unsecure(LOOSE)?	_____ yes		<input checked="" type="checkbox"/> no		
B. Improper position (DISCP)?	_____ yes		<input checked="" type="checkbox"/> no		

If any of the above conditions exist, note:

Affected Part (I, II, III or IV)	Condition (Observation Code)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Notes / Comments

Table 29
Igniter Heater Component - Evaluation Checkoff Worksheet

Inspector(s): Elgie Hale						
Motor No.:			Side: <input checked="" type="checkbox"/> Left <input checked="" type="checkbox"/> Right		Date: 5/7/89	
Joint: Igniter (IGN)		Case End: Igniter Adapter (FWD)			Component: JPS	

I. T-Bolt Latch Band Clamp Assembly Intact (BAND)?	yes	no
II. Igniter Heater		
A. Delaminations (DLHTR)?	yes	no
B. Discolorations (DSCLR)?	yes	no
C. Charred (HTAFF)?	yes	no
D. Warped (HTAFF)?	yes	no
III. Heater Power Cables		
A. Not Intact (LOOSE)?	yes	no
B. Charred (HTAFF)?	yes	no

If any of the above conditions exist, note:

Affected Part (I, II or III)	Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)

Notes / Comments